



## Centennial Monument Site Enhancement

### Overview:



- Picnic tables at the Moberly Centennial Monument were identified to be in unsafe condition.
- Tables were marked off, safely dismantled and moved to the site of the new picnic table.



- New site was measured and excavated next to the Moberly Community Orchard
- Remains of dismantled picnic tables were re-used to create a design for new picnic table base
- Bolts for replacement picnic table were measured and set into the concrete as it was poured



- New picnic table purchased from independent craftsman in Dawson Creek, B.C. and driven back to the Boreal Centre's Moberly Lake property to be prepared for installation.
- Table was stained by Boreal Centre employees, and epoxy resin was applied to the surface.



- Table was then mounted onto the newly created picnic table base, and securely bolted in.
- Boreal Centre employees also repainted the steel railing that surrounds the Memorial Cairn.
- A bear-proof garbage can was added to the site and bolted into a similar concrete platform by Boreal Centre Employees.

